

EAST Search History

| Ref # | Hits | Search Query | DBs | Default Operator | Plurals | Time Stamp |
|-------|------|---|------------------------------------|------------------|---------|------------------|
| L1 | 16 | (US-20030201894-\$ or US-20020171540-\$ or US-20030048180-\$). did. or (US-4482885-\$ or US-4495484-\$ or US-4871994-\$ or US-5015991-\$ or US-6489889-\$ or US-5926088-\$ or US-5038135-\$ or US-6300869-\$ or US-5304981-\$ or US-5659291-\$ or US-6300868-\$ or US-6124789-\$). did. or (EP-462339-\$). did. | US-PGPUB; USPAT; DERWENT | OR | ON | 2009/01/27 09:37 |
| L2 | 0 | L1 and button near3 (start engine) | US-PGPUB; USPAT; EPO; JPO; DERWENT | OR | ON | 2009/01/27 09:38 |
| L3 | 280 | button near3 start near3 engine | US-PGPUB; USPAT; EPO; JPO; DERWENT | OR | ON | 2009/01/27 09:38 |
| L4 | 62 | button near3 start near3 engine and "340".clas. | US-PGPUB; USPAT; EPO; JPO; DERWENT | OR | ON | 2009/01/27 09:39 |
| L5 | 1 | "10570591" and button | US-PGPUB; USPAT; EPO; JPO; DERWENT | OR | ON | 2009/01/27 09:39 |

1/27/2009 9:52:30 AM

C:\ Documents and Settings\kmcnally\ My Documents\ EAST\ Workspaces\ 10570591 warning system for vehicle - gear shift detector.wsp